


Vehicle Detail Report

Kia Seltos 2023 1.5L IVT Luxury Edition

Basic Information

Brand	Kia
Mileage	13,000 km
Color	White
First Registration	2024-01-01
Transfer Count	1

Vehicle Images





Vehicle Condition

1. Right rocker panel, Outer-side deformation, Inner side cracking (not accident-related). 2. Driver's seat rails and frame, Signs of removal. 3. Front passenger seat rails and frame, Signs of removal. 4. Headliner, Deformation, Soiling. 5. Front bumper, Scratch damage. 6. Rear bumper, Scratch damage. 7. Left front door, Scratch damage, Deformation. 8. Right front door, Paint repair, Body panel repair. 9. Left rear door, Scratch. 10. Right rear door, Deformation. 11. Right rear quarter panel, Deformation. 12. Headliner, Deformation, Soiling.

- "●" = Standard equipment
- "_ " = Not available
- "○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.