Vehicle Detail Report

Hyundai Tucson 2022 Tucson L 2.0L HEV LUX Hybrid Premium Edition

Basic Information

Brand	**Hyundai**
Mileage	**72,000 km**
Color	**White**
First Registration	**2022-05-01**
Transfer Count	**1**

Vehicle Images


















Vehicle Condition

1. Left, B, Column Sealing, Inner side of left B-pillar, Scratch, Non-accident-related deformation. 2. Trunk floor, Spare wheel well, Soiling. 3. Driver’s seat slide rail, Driver's seat rails and frame, Signs of removal. 4. Passenger seat track, Front passenger seat rails and frame, Signs of removal. 5. Driver's seat, Driver's seat, Damage.

"●" = Standard equipment

"-" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.