

Vehicle Detail Report

BYD Dolphin 2021 Fashion Edition

Basic Information

Brand	BYD
Mileage	40,000 km
Color	Other
First Registration	2022-12-01
Transfer Count	0

Vehicle Images





Vehicle Condition

1. Left front door, Paint repair. 2. Right front door, Body panel repair. 3. Right rear door, Body panel repair. 4. Left front fender, Paint repair. 5. Right front fender, Body panel repair. 6. Right rear quarter panel, Body panel repair.

"●" = Standard equipment

"_" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.