Vehicle Detail Report

Hyundai Tucson 2023 Tucson L 1.5T LUX Two-wheel-drive Prestige Edition

Basic Information

Brand	**Hyundai**
Mileage	**8,000 km**
Color	**White**
First Registration	**2023-03-01**
Transfer Count	**0**

Vehicle Images

























Vehicle Condition

1. Left bottom side member, Left rocker panel, Scratch damage. 2. Left, C, Column Sealing, Inner side of left C-pillar, Scratch.

"●" = Standard equipment

"-" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.