

Vehicle Detail Report

Jetour X70 PRO 2023 1.5T DCT Comfortable 5 seat

Basic Information

Brand	Jetour
Mileage	39,000 km
Color	Dark gray
First Registration	2023-09-01
Transfer Count	1

Vehicle Images







Vehicle Condition

1. Left rocker panel, Outer-side deformation. 2. Right rocker panel, Corrosion. 3. Inner side of left A-pillar, Deformation. 4. Hood, Deformation. 5. Front bumper, Deformation, Scratch damage. 6. Left front door, Scratch damage. 7. Right front door, Deformation. 8. Right front fender, Scratch damage.

"●" = Standard equipment

"-" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.