Vehicle Detail Report

Chery Tiggo 8 2025 Premium Edition 230TCI Automatic Luxury Edition

Basic Information

Brand	**Chery**
Mileage	**28,000 km**
Color	**Black**
First Registration	**2024-12-01**
Transfer Count	**0**

Vehicle Images












Vehicle Condition

1. Left bottom side member, Left rocker panel, Scratch damage. 2. Right bottom edge beam, Right rocker panel, Scratch damage. 3. Left, C, Column Sealing, Inner side of left C-pillar, Scratch. 4. Right, C, Column Sealing, Inner side of right C-pillar, Scratch. 5. Trunk floor, Spare wheel well, Soiling. 6. Driver’s seat slide rail, Driver's seat rails and frame, Signs of removal. 7. Passenger seat track, Front passenger seat rails and frame, Signs of removal. 8. Headliner, Soiling. 9. Right rear quarter panel, Scratch. 10. Driver's seat, Driver's seat, Soiling. 11. Headliner, Soiling.

"●" = Standard equipment

"-" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.