Vehicle Detail Report

Jetour T2 2025 2.0TD XWD Discovery

Basic Information

Brand	**Jetour**
Mileage	**20,000 km**
Color	**Black**
First Registration	**2024-11-01**
Transfer Count	**0**


Vehicle Images




















Vehicle Condition

1. Left rear quarter panel: Paint repair.

"●" = Standard equipment

"-" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.