

Vehicle Detail Report

Hyundai ix35 2021 240T GDi DCT Two-wheel drive leading version GLS

Basic Information

| | |
|--------------------|------------|
| Brand | Hyundai |
| Mileage | 61,000 km |
| Color | White |
| First Registration | 2021-01-01 |
| Transfer Count | 0 |

Vehicle Images





Vehicle Condition

1. Trunk lid, Paint repair. 2. Right front fender, Paint repair. 3. Right rear quarter panel, Paint repair. 4. Right side, C, column triangular glass, Replaced. 5. Rear windshield, Replaced. 6. Right headlight, Signs of removal.

"●" = Standard equipment

"_" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.