

# Vehicle Detail Report

## Hyundai Sonata 2015 1.6T GLX Leading Type

### Basic Information

Brand	Hyundai
Mileage	98,000 km
Color	Champagne color
First Registration	2015-06-01
Transfer Count	0

### Vehicle Images





## Vehicle Condition

1. Left upper side rail, Paint repair. 2. Inner side of left C-pillar, Paint repair. 3. Left rear quarter panel, Paint repair. 4. Right rear quarter panel, Paint repair, Body panel repair.

"●" = Standard equipment

"\_" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.