


Vehicle Detail Report

Geely Coolray 2025 Coolray L 1.5TD DCT Battle version

Basic Information

Brand	Geely
Mileage	10,000 km
Color	White
First Registration	2024-11-01
Transfer Count	0

Vehicle Images





Vehicle Condition

1. Front bumper, Paint chip, Deformation. 2. Rear bumper, Scratch damage. 3. Left front door, Paint chip, Deformation. 4. Right front door, Paint chip, Deformation. 5. Right rear door, Paint chip. 6. Trunk lid, Deformation. 7. Left front fender, Paint chip. 8. Left tail light, Scratch. 9. Right tail light, Scratch.

"●" = Standard equipment

"_" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.