

Vehicle Detail Report

Hyundai ix25 2015 1.6L Automatic two-drive intelligent type GLS

Basic Information

Brand	Hyundai
Mileage	96,100 km
Color	White
First Registration	2015-02-01
Transfer Count	1

Vehicle Images





Vehicle Condition

1. Left, B, Column Sealing, Inner side of left B-pillar, Dent. 2. Right rear quarter panel, Scratch damage.

- "●" = Standard equipment
- "_" = Not available
- "○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.