


# Vehicle Detail Report

## Jetour X70M 2020 1.5T Manual Value Partner

### Basic Information

Brand	Jetour
Mileage	55,000 km
Color	Black
First Registration	2022-04-01
Transfer Count	1

### Vehicle Images





## Vehicle Condition

1. Corrosion. 2. Right rear door, Paint repair. 3. Right front fender, Body panel repair.

"●" = Standard equipment

"\_" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.