Vehicle Detail Report

BMW i7 2023 eDrive50L Leading Type M Sports suit

Basic Information


Brand	**BMW**
Mileage	**48,000 km**
Color	**Dark gray**
First Registration	**2024-01-01**
Transfer Count	**3**

Vehicle Images
























Vehicle Condition

1. Right bottom edge beam, Right rocker panel, Scratch damage. 2. Driver’s seat slide rail, Driver's seat rails and frame, Signs of removal. 3. Passenger seat track, Front passenger seat rails and frame, Signs of removal. 4. Front subframe, Signs of removal.

"●" = Standard equipment

"-" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.