Vehicle Detail Report

Hyundai Tucson 2025 Tucson L 1.5T LUX Premium Edition N-Line

Basic Information

Brand	**Hyundai**
Mileage	**4,000 km**
Color	**Dark gray**
First Registration	**2025-03-01**
Transfer Count	**0**

Vehicle Images



























Vehicle Condition

1. Left bottom side member: Left rocker panel, Scratch damage. 2. Right rear quarter panel: Paint chip, Scratch.

"●" = Standard equipment

"-" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.