

Vehicle Detail Report

Hyundai Encino 2018 1.6T Zhilian Edition

Basic Information

Brand	Hyundai
Mileage	110,000 km
Color	White
First Registration	2020-07-01
Transfer Count	0

Vehicle Images





Vehicle Condition

1. Left rocker panel, Outer-side deformation. 2. Right rocker panel, Outer-side deformation. 3. Inner side of left B-pillar, Non-accident-related deformation. 4. Driver's seat, Damage.

"●" = Standard equipment

"_" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.