

Vehicle Detail Report


Hyundai Tucson 2021 Tucson L 1.5T GLX Two-wheel drive elite version

Basic Information

Brand	Hyundai
Mileage	43,000 km
Color	White
First Registration	2023-01-01
Transfer Count	0

Vehicle Images







Vehicle Condition

1. Inner side of left B-pillar, Non-accident-related deformation. 2. Inner side of right C-pillar, Non-accident-related deformation. 3. Body floor pan, Aftermarket underbody coating.

"●" = Standard equipment

"_" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.