


Vehicle Detail Report


Changan CS75 2018 280T Auto Smart

Basic Information

Brand	Changan
Mileage	52,000 km
Color	Coffee color
First Registration	2018-09-01
Transfer Count	0

Vehicle Images





Vehicle Condition

1. Left rear quarter panel, Body panel repair.

"●" = Standard equipment

"_" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.