


Vehicle Detail Report

Jetour X90 PRO 2024 1.6TD DCT The perfect edition

Basic Information

Brand	Jetour
Mileage	40,000 km
Color	White
First Registration	2024-12-01
Transfer Count	0

Vehicle Images





Vehicle Condition

1. Radiator support, Signs of removal, Replaced. 2. Right front frame rail, Corrosion. 3. Left bottom side member, Left rocker panel, Scratch damage, Outer-side deformation. 4. Right bottom edge beam, Right rocker panel, Scratch damage. 5. Trunk floor, Spare wheel well, Dust and sand residue, Water stains. 6. Headliner, Soiling. 7. Headliner, Soiling.

"●" = Standard equipment

"_" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.