

Vehicle Detail Report


Jetour X70 PLUS 2021 1.5T 6MT wind 5 seat

Basic Information

Brand	Jetour
Mileage	28,000 km
Color	White
First Registration	2021-10-01
Transfer Count	0

Vehicle Images





Vehicle Condition

1. Left rear frame rail, Corrosion. 2. Right rear frame rail, Corrosion. 3. Left bottom side member, Left rocker panel, Inner-side deformation. 4. Rear body panel, Corrosion. 5. Right rear quarter panel, Paint repair, Body panel repair.

"●" = Standard equipment

"□" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.