

Vehicle Detail Report

Jetour Dasheng 2025 1.5T DCT Flagship

Basic Information

Brand	Jetour
Mileage	22,000 km
Color	Dark gray
First Registration	2025-02-01
Transfer Count	0

Vehicle Images







Vehicle Condition

1. Left upper side rail, Deformation. 2. Hood, Deformation. 3. Front bumper, Paint repair. 4. Rear bumper, Scratch damage. 5. Left front door, Paint chip. 6. Right front door, Paint chip, Deformation. 7. Left rear door, Deformation, Scratch. 8. Right rear door, Deformation. 9. Left front fender, Scratch damage. 10. Right front fender, Paint repair. 11. Left rear quarter panel, Deformation. 12. Front passenger seat, Damage.

-
- "●" = Standard equipment
- "-" = Not available
- "○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.