

# Vehicle Detail Report


## Volkswagen Lamando 2022 Lamando L 280TSI DSG Spicy Edition

### Basic Information

Brand	Volkswagen
Mileage	20,000 km
Color	Black
First Registration	2022-11-01
Transfer Count	0

### Vehicle Images





## Vehicle Condition

1. Right rocker panel, Outer-side deformation. 2. Left rear quarter panel, Paint repair, Body panel repair.

"●" = Standard equipment

"-" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.