

# Vehicle Detail Report

Volkswagen T-Cross 2019 280TSI DSG Two-wheel drive comfort model China V

## Basic Information

Brand	Volkswagen
Mileage	80,000 km
Color	White
First Registration	2019-04-01
Transfer Count	0

## Vehicle Images





## Vehicle Condition

1. Radiator support, Signs of removal. 2. Driver's seat rails and frame, Signs of removal. 3. Right rear quarter panel, Paint repair.

---

"●" = Standard equipment

"-" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.