

# Vehicle Detail Report

Exeed VX 2023 2.0T Four-wheel drive star honor Six seats

## Basic Information

Brand	Exeed
Mileage	69,000 km
Color	Black
First Registration	2023-04-01
Transfer Count	0

## Vehicle Images





## Vehicle Condition

1. Left rocker panel, Outer-side deformation. 2. Hood, Scratch. 3. Front bumper, Paint repair, Replaced, Scrape, Signs of removal. 4. Rear bumper, Paint chip, Scrape. 5. Left front door, Deformation, Scratch. 6. Right front door, Paint chip, Deformation, Scrape. 7. Left rear door, Paint chip, Deformation, Scrape, Scratch. 8. Right rear door, Paint chip, Scratch. 9. Trunk lid, Paint chip, Scratch. 10. Left front fender, Paint chip, Scratch. 11. Left rear quarter panel, Paint chip, Scratch, Scrape, Deformation. 12. Left headlight, Signs of removal, Replaced.

---

"●" = Standard equipment

"-" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.