


Vehicle Detail Report

Hyundai ix35 2019 2.0L Automatic two-wheel drive Zhiyong Enjoyment Edition China V

Basic Information

Brand	Hyundai
Mileage	73,000 km
Color	White
First Registration	2019-06-01
Transfer Count	1

Vehicle Images





Vehicle Condition

1. Left front strut tower, Corrosion. 2. Right front strut tower, Corrosion. 3. Radiator support, Deformation, Corrosion. 4. Right front frame rail, Corrosion. 5. Right, B, Column Sealing, Inner side of right B-pillar, Scratch, Dent. 6. Trunk floor, Spare wheel well, Corrosion, Paint repair.

"●" = Standard equipment

"_" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.