

Vehicle Detail Report

Hyundai ix35 2012 2.0L Automatic two-wheel drive elite version GLS

Basic Information

Brand	Hyundai
Mileage	124,000 km
Color	Yellow
First Registration	2013-06-01
Transfer Count	0

Vehicle Images





Vehicle Condition

1. Left front strut tower, Corrosion. 2. Right front strut tower, Corrosion. 3. Left front frame rail, Crack, Corrosion. 4. Right front frame rail, Corrosion. 5. Right rear frame rail, Corrosion. 6. Left, B, Column Sealing, Inner side of left B-pillar, Scratch. 7. Right, A, Column Sealing, Inner side of right A-pillar, Deformation. 8. Left front fender lining, Left front fender structure, Corrosion. 9. Right front fender lining, Right front fender structure, Corrosion. 10. Rear body panel, Corrosion.

"●" = Standard equipment

"□" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.