


Vehicle Detail Report

Honda Civic 2022 240TURBO CVT Move ·C
Guest Special Edition

Basic Information

Brand	Honda
Mileage	20,000 km
Color	White
First Registration	2025-01-01
Transfer Count	0

Vehicle Images





Vehicle Condition

1. Inner side of left B-pillar, Non-accident-related deformation. 2. Left rear quarter panel, Deformation.

"●" = Standard equipment

"_" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.