

Vehicle Detail Report

Hyundai ix35 2019 2.0L Automatic two-wheel drive Zhiyong Enjoyment Edition Country VI

Basic Information

Brand	Hyundai
Mileage	98,000 km
Color	Black
First Registration	2019-01-01
Transfer Count	1

Vehicle Images





Vehicle Condition

1. Left bottom side member, Left rocker panel, Scratch damage. 2. Left, B, Column Sealing, Inner side of left B-pillar, Non-accident-related deformation. 3. Left, C, Column Sealing, Inner side of left C-pillar, Deformation. 4. Right, B, Column Sealing, Inner side of right B-pillar, Non-accident-related deformation. 5. Left rear quarter panel, Paint repair, Body panel repair.

"●" = Standard equipment

"_" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.