

Vehicle Detail Report

Hyundai ix35 2019 2.0L Automatic two-wheel drive Zhiyong Enjoyment Edition Country VI

Basic Information

Brand	Hyundai
Mileage	92,000 km
Color	White
First Registration	2020-03-01
Transfer Count	0

Vehicle Images





Vehicle Condition

1. Inner side of left B-pillar, Scratch, Non-accident-related deformation.
2. Rear body panel, Corrosion.
3. Spare wheel well, Corrosion.
4. Driver's seat rails and frame, Corrosion.
5. Front passenger seat rails and frame, Corrosion.
6. Headliner, Soiling.
7. Headliner, Soiling.

"●" = Standard equipment

"□" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.