

Vehicle Detail Report

Chery Arrizo 8 2022 1.6TGDI DCT elegance

Basic Information

Brand	Chery
Mileage	29,000 km
Color	Black
First Registration	2023-11-01
Transfer Count	0

Vehicle Images





Vehicle Condition

1. Left front strut tower, Corrosion. 2. Left rear frame rail, Corrosion. 3. Right rear frame rail, Corrosion. 4. Left, B, Column Sealing, Inner side of left B-pillar, Non-accident-related deformation. 5. Rear body panel, Corrosion. 6. Left rear quarter panel, Paint repair, Body panel repair. 7. Right rear quarter panel, Paint repair, Body panel repair.

- "●" = Standard equipment
- "_" = Not available
- "○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.