

Vehicle Detail Report

Volkswagen CC 2015 2.0TSI Supreme Type

Basic Information

Brand	Volkswagen
Mileage	131,000 km
Color	Yellow
First Registration	2015-07-01
Transfer Count	1

Vehicle Images





Vehicle Condition

1. Corrosion. 2. Heavy wear. 3. Oil leak. 4. Left front door, Paint repair. 5. Right front door, Body panel repair. 6. Left rear door, Body panel repair. 7. Right rear door, Paint repair. 8. Left front fender, Replaced. 9. Right front fender, Body panel repair. 10. Left rear quarter panel, Body panel repair. 11. Right rear quarter panel, Body panel repair. 12. Left rocker panel exterior trim, Scratch damage. 13. Right rocker panel exterior trim, Scratch damage. 14. Corrosion.

"●" = Standard equipment

"-" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.