


# Vehicle Detail Report

## Mercedes-Benz CLS 2012 AMG CLS 63

### Basic Information

Brand	Mercedes-Benz
Mileage	107,400 km
Color	Black
First Registration	2012-02-01
Transfer Count	1

### Vehicle Images







## Vehicle Condition

1. Radiator support, Signs of removal. 2. Driver's seat rails and frame, Signs of removal. 3. Front passenger seat rails and frame, Signs of removal. 4. Right rear quarter panel, Paint repair.

---

"●" = Standard equipment

"\_" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.