

Vehicle Detail Report


Jetour X90 2019 1.5T DCT Smart Enjoyment 5 seat Country VI

Basic Information

Brand	Jetour
Mileage	140,000 km
Color	Black
First Registration	2019-10-01
Transfer Count	0

Vehicle Images







Vehicle Condition

1. Valve cover gasket, Signs of removal. 2. Hood, Paint repair. 3. Right rear door, Body panel repair. 4. Left headlight, Signs of removal.

"●" = Standard equipment

"_" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.