Vehicle Detail Report

Honda CR-V 2020 Shining Edition 240TURBO CVT 2WD Comfort Version

Basic Information


Brand	**Honda**
Mileage	**79,000 km**
Color	**White**
First Registration	**2020-06-01**
Transfer Count	**0**

Vehicle Images












Vehicle Condition

1. Left bottom side member, Left rocker panel, Scratch damage. 2. Left, B, Column Sealing, Inner side of left B-pillar, Scratch, Non-accident-related deformation. 3. Right, C, Column Sealing, Inner side of right C-pillar, Scratch. 4. Driver’s seat slide rail, Driver's seat rails and frame, Signs of removal. 5. Passenger seat track, Front passenger seat rails and frame, Signs of removal. 6. Headliner, Soiling. 7. Left rear quarter panel, Deformation. 8. Headliner, Soiling.

"●" = Standard equipment

"-" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.