

Vehicle Detail Report

Honda Accord 2023 Sharp ·T move 260TURBO
Smart Edition

Basic Information

Brand	Honda
Mileage	46,000 km
Color	Black
First Registration	2023-09-01
Transfer Count	0

Vehicle Images





Vehicle Condition

1. Right rocker panel, Scratch damage. 2. Driver's seat rails and frame, Signs of removal. 3. Front passenger seat rails and frame, Signs of removal. 4. Left rear quarter panel, Scrape, Deformation. 5. Right rear quarter panel, Deformation. 6. Body floor pan, Deformation.

"●" = Standard equipment

"_" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.