

Vehicle Detail Report

Changan CS85 COUPE 2019 1.5T Type Version

Basic Information

Brand	Changan
Mileage	75,000 km
Color	White
First Registration	2020-09-01
Transfer Count	0

Vehicle Images





Vehicle Condition

1. Spare wheel well, Soiling.

"●" = Standard equipment

"□" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.