

Vehicle Detail Report

Toyota Levin 2023 Dual Power 1.8L Luxury Edition

Basic Information

Brand	Toyota
Mileage	14,000 km
Color	White
First Registration	2023-10-01
Transfer Count	1

Vehicle Images







Vehicle Condition

1. Driver’s seat slide rail, Driver's seat rails and frame, Signs of removal. 2. Passenger seat track, Front passenger seat rails and frame, Signs of removal. 3. Hood, Hood, Paint chip, Scratch. 4. Front bumper, Scratch damage. 5. Rear bumper, Scratch damage. 6. Left front door, Paint chip, Scratch. 7. Right front door, Paint chip, Scratch. 8. Left rear door, Scratch. 9. Right rear door, Paint chip. 10. Trunk lid, Trunk lid, Paint repair, Body panel repair. 11. Right front fender, Scratch. 12. Left rear quarter panel, Scratch. 13. Right rear quarter panel, Scratch. 14. Windshield, Stone chip. 15. Right headlight, Scratch. 16. Left tail light, Scratch.

"●" = Standard equipment

"-" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.