

Vehicle Detail Report

Jetour Freedom 2025 1.5TD Discover

Basic Information

Brand	Jetour
Mileage	17,000 km
Color	Black
First Registration	2025-09-01
Transfer Count	0

Vehicle Images







Vehicle Condition

1. Right roof side member, Right upper side rail, Scratch. 2. Left bottom side member, Left rocker panel, Scratch damage. 3. Hood, Hood, Scratch. 4. Front bumper, Scratch damage. 5. Rear bumper, Scratch damage. 6. Left front door, Paint chip, Deformation, Scratch. 7. Left rear door, Scratch. 8. Right rear door, Paint chip, Deformation, Scratch. 9. Left front fender, Paint chip, Scratch damage. 10. Right front fender, Scratch. 11. Right rear quarter panel, Scratch. 12. Windshield, Scratch. 13. Left headlight, Scratch. 14. Left tail light, Scratch. 15. Right tail light, Scratch.

- "●" = Standard equipment
- "_" = Not available
- "○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.