Vehicle Detail Report

Mercedes-Benz CLE 2024 AMG CLE 53 4MATIC+ Coupe

Basic Information

Brand	**Mercedes-Benz**
Mileage	**13,000 km**
Color	**White**
First Registration	**2024-11-01**
Transfer Count	**0**

Vehicle Images


















Vehicle Condition

1. Right roof side member: Right upper side rail, Paint repair. 2. Driver’s seat slide rail: Driver's seat rails and frame, Signs of removal. 3. Passenger seat track: Front passenger seat rails and frame, Signs of removal. 4. Right rear quarter panel: Paint repair, Body panel repair.

"●" = Standard equipment

"-" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.