

Vehicle Detail Report

Toyota Corolla 2017 Restyling 1.2T S-CVT GL-i
China V

Basic Information

Brand	Toyota
Mileage	70,000 km
Color	Champagne color
First Registration	2017-12-01
Transfer Count	0

Vehicle Images





Vehicle Condition

1. Left rocker panel, Scratch damage, Outer-side deformation. 2. Right rocker panel, Scratch damage, Outer-side deformation. 3. Inner side of left B-pillar, Scratch, Dent. 4. Driver's seat rails and frame, Corrosion, Signs of removal. 5. Front passenger seat rails and frame, Corrosion, Signs of removal. 6. Left rear quarter panel, Paint chip, Scratch, Deformation.

-
- "●" = Standard equipment
 - "_" = Not available
 - "○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.