

Vehicle Detail Report

Jetour X70 PRO 2023 1.5T DCT Comfortable 5 seat

Basic Information

Brand	Jetour
Mileage	44,000 km
Color	Black
First Registration	2023-10-01
Transfer Count	0

Vehicle Images





Vehicle Condition

1. Driver's seat rails and frame, Signs of removal. 2. Front passenger seat rails and frame, Signs of removal. 3. Hood, Deformation, Scratch. 4. Front bumper, Paint chip, Scrape. 5. Rear bumper, Scrape. 6. Left front door, Paint chip, Deformation, Corrosion, Paint repair, Body panel repair, Scratch. 7. Right front door, Paint chip, Deformation, Scratch. 8. Left rear door, Paint chip, Paint repair, Body panel repair, Deformation, Scratch. 9. Right rear door, Scratch. 10. Trunk lid, Scratch. 11. Left front fender, Scratch. 12. Right front fender, Scratch. 13. Left rear quarter panel, Scratch. 14. Right rear quarter panel, Scratch. 15. Windshield, Stone chip. 16. Left headlight, Water stain. 17. Right headlight, Scratch. 18. Left tail light, Scratch. 19. Right tail light, Scratch.

"●" = Standard equipment

"□" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.