

Vehicle Detail Report

Volkswagen T-Cross 2023 Restyling 1.5L Automatic Fashion Edition


Basic Information

Brand	Volkswagen
Mileage	68,400 km
Color	White
First Registration	2024-01-01
Transfer Count	0

Vehicle Images







Vehicle Condition

1. Corrosion. 2. Right front door, Body panel repair. 3. Left rear door, Replaced. 4. Right rear door, Body panel repair. 5. Left front fender, Body panel repair. 6. Right front fender, Body panel repair. 7. Right rear quarter panel, Body panel repair. 8. Windshield, Replaced.

"●" = Standard equipment

"-" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.