

Vehicle Detail Report

Jetour X70 PLUS 2022 1.6T DCT ground Pro 5 seat

Basic Information

Brand	Jetour
Mileage	35,000 km
Color	White
First Registration	2022-07-01
Transfer Count	0

Vehicle Images







Vehicle Condition

1. Left rocker panel, Scratch damage. 2. Right rocker panel, Scratch damage, Corrosion, Outer-side deformation. 3. Front bumper, Scrape. 4. Rear bumper, Scratch damage. 5. Left front door, Deformation, Scratch. 6. Right front door, Scratch. 7. Left rear door, Deformation, Scrape. 8. Right rear door, Scratch. 9. Left front fender, Deformation. 10. Right front fender, Deformation, Scrape. 11. Left rear quarter panel, Scratch. 12. Right tail light, Scratch. 13. Driver's seat, Wear.

"●" = Standard equipment

"_" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.