


Vehicle Detail Report

Volkswagen T-Cross 2023 Restyling 1.5L Automatic Fashion Edition

Basic Information

Brand	Volkswagen
Mileage	72,000 km
Color	White
First Registration	2024-01-01
Transfer Count	1

Vehicle Images





Vehicle Condition

1. Front bumper, Paint repair, Scrape. 2. Rear bumper, Scrape. 3. Left front door, Deformation, Paint repair, Body panel repair. 4. Right front door, Paint repair, Body panel repair. 5. Left rear door, Paint chip, Paint repair, Body panel repair. 6. Right rear door, Paint repair, Body panel repair. 7. Right front fender, Paint repair, Deformation. 8. Left rear quarter panel, Paint repair, Body panel repair. 9. Right rear quarter panel, Paint repair, Body panel repair.

"●" = Standard equipment

"-" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.