

Vehicle Detail Report

MG MG5 2026 300TGI Global Ultimate

Basic Information

Brand	MG
Mileage	3,000 km
Color	Dark gray
First Registration	2025-08-01
Transfer Count	0

Vehicle Images





Vehicle Condition

1. Right rocker panel, Paint repair, Outer-side deformation, Outer-side body panel repair. 2. Right rear quarter panel, Paint repair, Body panel repair.

"●" = Standard equipment

"_" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.