


# Vehicle Detail Report



## Volkswagen Lamando 2024 Lamando L 280TSI DSG Spicy Edition

### Basic Information

Brand	Volkswagen
Mileage	32,000 km
Color	White
First Registration	2024-07-01
Transfer Count	0

### Vehicle Images





## Vehicle Condition

1. Left rocker panel, Scratch damage. 2. Right rocker panel, Paint repair, Outer-side body panel repair. 3. Driver's seat rails and frame, Signs of removal. 4. Front passenger seat rails and frame, Signs of removal. 5. Left rear quarter panel, Paint chip, Scratch damage.

---

"●" = Standard equipment

"□" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.