

Vehicle Detail Report

Hyundai ix25 2019 1.6L Automatic Intelligent Commemorative

Basic Information

Brand	Hyundai
Mileage	121,000 km
Color	White
First Registration	2019-03-01
Transfer Count	0

Vehicle Images







Vehicle Condition

1. Left, B, Column Sealing, Inner side of left B-pillar, Scratch. 2. Trunk floor, Spare wheel well, Corrosion. 3. Driver's seat slide rail, Driver's seat rails and frame, Corrosion. 4. Left rear quarter panel, Scrape. 5. Right rear quarter panel, Deformation.

"●" = Standard equipment

"-" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.