


Vehicle Detail Report

Hyundai ix35 2019 2.0L Automatic two-wheel drive Zhiyong Enjoyment Edition Country VI

Basic Information

Brand	Hyundai
Mileage	70,000 km
Color	White
First Registration	2019-03-01
Transfer Count	0

Vehicle Images





Vehicle Condition

1. Left, B, Column Sealing, Inner side of left B-pillar, Non-accident-related deformation. 2. Trunk floor, Spare wheel well, Paint repair. 3. Driver's seat slide rail, Driver's seat rails and frame, Signs of removal.

"●" = Standard equipment

"_" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.