

Vehicle Detail Report

BMW Z4 2019 M40i M Sport performance models

Basic Information

Brand	BMW
Mileage	60,000 km
Color	Red
First Registration	2021-07-01
Transfer Count	4

Vehicle Images





Vehicle Condition

1. Rear body panel, Paint repair, Body panel repair.

-
- "●" = Standard equipment
 - "_ " = Not available
 - "○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.