


# Vehicle Detail Report



Jetour X90 PLUS 2024 1.6TD DCT Villa PRO

## Basic Information

|                    |            |
|--------------------|------------|
| Brand              | Jetour     |
| Mileage            | 8,000 km   |
| Color              | Black      |
| First Registration | 2024-01-01 |
| Transfer Count     | 0          |

## Vehicle Images





## Vehicle Condition

1. Inner side of right C-pillar, Scratch. 2. Hood, Scratch. 3. Front bumper, Scratch damage, Signs of removal. 4. Rear bumper, Scratch damage. 5. Left front door, Paint chip, Scratch. 6. Right front door, Scratch. 7. Left rear door, Scratch. 8. Right rear door, Scratch. 9. Left front fender, Scratch. 10. Right front fender, Scratch. 11. Left rear quarter panel, Scratch. 12. Right rear quarter panel, Scratch.

---

"●" = Standard equipment

"□" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.