Vehicle Detail Report

Hyundai ix35 2019 2.0L Automatic Two-Wheel Drive Smart Courage Enjoyment China VI

Basic Information

Brand	**Hyundai**
Mileage	**90,000 km**
Color	**Black**
First Registration	**2019-01-01**
Transfer Count	**2**

Vehicle Images
















Vehicle Condition

1. Left bottom side member: Left rocker panel, Scratch damage. 2. Left B-pillar edge: Inner side of left B-pillar, Non-accident-related deformation. 3. Left C-pillar edge: Inner side of left C-pillar, Deformation. 4. Right B-pillar edge: Inner side of right B-pillar, Non-accident-related deformation. 5. Left rear quarter panel: Paint repair, Body panel repair.

"●" = Standard equipment

"-" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.